

### **ABSTRACT**

An optic fiber must be properly aligned with a laser in order to maximize optical power transmission. The fiber is aligned with a holder by welding the fiber to the holder. A screen is placed between the welds and the laser in order to protect the laser from weld splatter.

FBI Laboratory  
Washington, D.C.  
Case File Number: Joyce 26  
Date: 10/10/2008  
Report Number: 909853